



ART. 8313

| CODICE | Ø1 | Ø2 | A | B | C | D |
|-------------|--------|--------|----|----|----|----|
| 8313 12 | G1/2 | R1/2 | 38 | 25 | 34 | 21 |
| 8313 3412 | G3/4 | R1/2 | 37 | 30 | 31 | 18 |
| 8313 34 | G3/4 | R3/4 | 42 | 30 | 36 | 22 |
| 8313 134 | G1 | R3/4 | 40 | 37 | 34 | 22 |
| 8313 1 | G1 | R1 | 46 | 38 | 39 | 24 |
| 8313 1141 | G1 1/4 | R1 | 47 | 47 | 39 | 23 |
| 8313 114 | G1 1/4 | R1 1/4 | 55 | 47 | 48 | 30 |
| 8313 112114 | G1 1/2 | R1 1/4 | 51 | 54 | 42 | 24 |
| 8313 112 | G1 1/2 | R1 1/2 | 56 | 54 | 48 | 30 |
| 8313 2112 | G2 | R1 1/2 | 55 | 68 | 45 | 26 |
| 8313 2 | G2 | R2 | 64 | 68 | 56 | 34 |

Quote espresse in mm